

FIG. 1
(PRIOR ART)






FIG. 2
(PRIOR ART)



OPW2 OPW1 OPW0

OPTIMUM
PHASE
WIDTH




FIG. 3C




FIG. 4




FIG. 5




FIG. 6